

EXHIBIT 1



HIGH VOLTAGE




EXHIBIT 2

TL637 NEAR SANTA YSABEL



NOT TO SCALE



NOTE:
LOCATIONS SHOWN POSSIBLE DAMAGE;
AGE AND CAUSE PRESENTLY UNDETERMINED.
CALIFIRE HAS CUSTODY OF THE CONDUCTORS AND NO
FORENSIC TESTING HAS BEEN CONDUCTED OR
SCHEDULED THAT WOULD ENABLE SDG&E TO
ACCURATELY PROVIDE THE REQUESTED INFORMATION.